



MM	DECIMAL		INCH	DECIMAL	DIFFERENCE
10	0.3937	>	3/8	0.3750	-0.019
11	0.4331	=	7/16	0.4375	0.004
12	0.4724	<	1/2	0.5000	0.028
13	0.5118	=	1/2	0.5000	-0.012
14	0.5512	=	9/16	0.5625	0.011
15	0.5906	<	5/8	0.6250	0.034
16	0.6299	=	5/8	0.6250	-0.005
17	0.6693	<	11/16	0.6875	0.018
18	0.7087	>	11/16	0.6875	-0.021
19	0.7480	=	3/4	0.7500	0.002
20	0.7874	>	3/4	0.7500	-0.037
21	0.8268	=	13/16	0.8125	-0.014
22	0.8661	=	7/8	0.8750	0.009
23	0.9055	>	7/8	0.8750	-0.031
24	0.9449	=	15/16	0.9375	-0.007
25	0.9843	<	1	1.0000	0.016
26	1.0236	>	1	1.0000	-0.024
27	1.0630	=	1 1/16	1.0625	0.000
28	1.1024	<	1 1/8	1.1250	0.023
29	1.1417	>	1 1/8	1.1250	-0.017
30	1.1811	=	1 3/16	1.1875	0.006
31	1.2205	<	1 1/4	1.2500	0.030
32	1.2598	=	1 1/4	1.2500	-0.010
33	1.2992	=	1 5/16	1.3125	0.013
34	1.3386	>	1 5/16	1.3125	-0.026
35	1.3780	=	1 3/8	1.3750	-0.003
36	1.4173	<	1 7/16	1.4375	0.020
37	1.4567	>	1 7/16	1.4375	-0.019
38	1.4961	=	1 1/2	1.5000	0.004
39	1.5354	>	1 1/2	1.5000	-0.035
40	1.5748	=	1 9/16	1.5625	-0.012
41	1.6142	>	1 9/16	1.5625	-0.052
42	1.6535	>	1 5/8	1.6250	-0.029
43	1.6929	=	1 11/16	1.6875	-0.005
44	1.7323	<	1 3/4	1.7500	0.018
45	1.7717	>	1 3/4	1.7500	-0.022
46	1.8110	=	1 13/16	1.8125	0.001
47	1.8504	>	1 13/16	1.8125	-0.038
48	1.8898	=	1 7/8	1.8750	-0.015
49	1.9291	=	1 15/16	1.9375	0.008
50	1.9685	<	2	2.0000	0.031
51	2.0079	=	2	2.0000	-0.008
52	2.0472	<	2 1/16	2.0625	0.015
53	2.0866	>	2 1/16	2.0625	-0.024
54	2.1260	=	2 1/8	2.1250	-0.001

MM	DECIMAL		INCH	DECIMAL	DIFFERENCE
55	2.1654	<	2 3/16	2.1875	0.022
56	2.2047	>	2 3/16	2.1875	-0.017
57	2.2441	=	2 1/4	2.2500	0.006
58	2.2835	>	2 1/4	2.2500	-0.033
59	2.3228	=	2 5/16	2.3125	-0.010
60	2.3622	=	2 3/8	2.3750	0.013
61	2.4016	>	2 3/8	2.3750	-0.027
62	2.4409	=	2 7/16	2.4375	-0.003
63	2.4803	<	2 1/2	2.5000	0.020
64	2.5197	>	2 1/2	2.5000	-0.020
65	2.5591	=	2 9/16	2.5625	0.003
66	2.5984	<	2 5/8	2.6250	0.027
67	2.6378	=	2 5/8	2.6250	-0.013
68	2.6772	=	2 11/16	2.6875	0.010
69	2.7165	>	2 11/16	2.6875	-0.029
70	2.7559	=	2 3/4	2.7500	-0.006
71	2.7953	<	2 13/16	2.8125	0.017
72	2.8346	>	2 13/16	2.8125	-0.022
73	2.8740	=	2 7/8	2.8750	0.001
74	2.9134	<	2 15/16	2.9375	0.024
75	2.9528	>	2 15/16	2.9375	-0.015
76	2.9921	=	3	3.0000	0.008
77	3.0315	>	3	3.0000	-0.031
78	3.0709	=	3 1/16	3.0625	-0.008
79	3.1102	=	3 1/8	3.1250	0.015
80	3.1496	>	3 1/8	3.1250	-0.025
81	3.1890	=	3 3/16	3.1875	-0.001
82	3.2283	<	3 1/4	3.2500	0.022
83	3.2677	>	3 1/4	3.2500	-0.018
84	3.3071	=	3 5/16	3.3125	0.005
85	3.3465	<	3 3/8	3.3750	0.029
86	3.3858	=	3 3/8	3.3750	-0.011
87	3.4252	=	3 7/16	3.4375	0.012
88	3.4646	>	3 7/16	3.4375	-0.027
89	3.5039	=	3 1/2	3.5000	-0.004
90	3.5433	<	3 9/16	3.5625	0.019
91	3.5827	>	3 9/16	3.5625	-0.020
92	3.6220	=	3 5/8	3.6250	0.003
93	3.6614	<	3 11/16	3.6875	0.026
94	3.7008	=	3 11/16	3.6875	-0.013
95	3.7402	=	3 3/4	3.7500	0.010
96	3.7795	>	3 3/4	3.7500	-0.030
97	3.8189	=	3 13/16	3.8125	-0.006
98	3.8583	<	3 7/8	3.8750	0.017
99	3.8976	>	3 7/8	3.8750	-0.023
100	3.9370	=	3 15/16	3.9375	0.000
105	4.1339	=	4 1/8	4.1250	-0.009
108	4.2520	=	4 1/4	4.2500	-0.002

MM	DECIMAL		INCH	DECIMAL	DIFFERENCE
110	4.3307	>	4 5/16	4.3125	-0.018
115	4.5276	>	4 1/2	4.5000	-0.028
116	4.5669	=	4 9/16	4.5625	-0.004
117	4.6063	<	4 5/8	4.6250	0.019
120	4.7244	<	4 3/4	4.7500	0.026
125	4.9213	<	4 15/16	4.9375	0.016
130	5.1181	=	5 1/8	5.1250	0.007
135	5.3150	=	5 5/16	5.3125	-0.002
136	5.3543	<	5 3/8	5.3750	0.021
140	5.5118	=	5 1/2	5.5000	-0.012
145	5.7087	>	5 11/16	5.6875	-0.021
150	5.9055	>	5 7/8	5.8750	-0.031
155	6.1024	<	6 1/8	6.1250	0.023
160	6.2992	=	6 5/16	6.3125	0.013
165	6.4961	=	6 1/2	6.5000	0.004
170	6.6929	=	6 11/16	6.6875	-0.005
175	6.8898	=	6 7/8	6.8750	-0.015
180	7.0866	>	7 1/16	7.0625	-0.024
185	7.2835	>	7 1/4	7.2500	-0.033
190	7.4803	<	7 1/2	7.5000	0.020
195	7.6772	=	7 11/16	7.6875	0.010
200	7.8740	=	7 7/8	7.8750	0.001
210	8.2677	>	8 1/4	8.2500	-0.018
230	9.0551	=	9 1/16	9.0625	0.007
260	10.2362	=	10 1/4	10.2500	0.014
265	10.4331	=	10 7/16	10.4375	0.004